CIVIL-TECH CONSULTANTS AND ENGINEERS

Building & Highway Material Testing Laboratory

An ISO 9001:2008 Certified Company

NABL - Accredited Laboratory as per ISO / IEC-17025 : 2005

JAS-ANZ BSCIC ISO 9001 REGISTERED

Job No.: CTCE/BBMP/NJ/Consultants/28/2018-19

Dated: 06.03.2018

To,
Executive Engineer,
Dasarahalli Division,
BBMP, Bangalore.

Sir,

Sub: Consultancy Services for the work of Providing CC Camera at garbage Block spots in Ward No.15,BBMP,Bangalore.

Ref: 1) EE/DD/WO/103/17-18 Date : 06.12.2017

2) Job Code: 015-17-000033

We are herewith forwarding to **Mr. Naveen J,** 1st and Final Bill duly verified and certified that the work is satisfactory and for a Gross Value of Rs. 9,94,920/- (Rupees Nine Lakhs Ninety Four Thousand Nine Hundred and Twenty only) for further needful.

Thanking you,

Yours faithfully,
For Civil-Tech Consultants and Engineers

6.3.2018

Chief Executive Officer

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರ
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

#23/14, 7th Cross, 3rd Stage, 4th Block, Shakthi Ganapathi Nagara, Basaveshwaranagar, Bangalore-79.
Tele Fax : 23223227, Website : www.civiltechconsultants.com
E-mail : vishwanath.ia@civiltechconsultants.com / info@civiltechconsultants.com

Scanned by CamScanner

Photograph was taken at the time of Inspection (05.03.2018) Providing CC Camera at garbage Block spots in Ward No.15,BBMP,Bangalore.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ದಾಗಲಗುಂಟೆ. ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Scanned by CamScanner

Photograph was taken at the time of Inspection (05.03.2018) Providing CC Camera at garbage Block spots in Ward No.15,BBMP,Bangalore.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರ
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Scanned by CamScanner